

SERVICE BULLETIN		
To: For the attention of: Please copy to:	All Dealers/MEAM The Service Manager Aston Martin Technician(s) The Dealer Principal The Parts Manager	Reference: SB: 0209 Issued: August 2006
Model:	DB9 Coupe, Volante and V8 Vantage	Page 1 of 1
Subject:	Window Drop Glass Memory Loss	

Issue

It has been established in cold weather that some Door Modules do not respond to the door open command, consequently the window glass does not drop to the design intent causing the glass to catch the body. To resolve this concern new software has been released to reflash the door modules

Procedure

With all vehicle in-car protection fitted, proceed as follows:

1. Boot up the WDS unit
2. Ensure you have re-ghosted the WDS with Ghost Disc 2, and have a freshly installed CD012
3. Connect WDS to the vehicle
4. Configure Drivers and Passenger Door Modules as EXISTING only
5. WDS will now download the correct software based on your initial VIN input
6. When the reflash is completed carry out Body DTC Read and Clear. Disconnect WDS
7. Reset the window drop glass memory and check window operation

Warranty Information

This Service Bulletin should be carried out on a complaint basis only.

Repair Operation Code: 00.06.AD Repair Operation Time: 0.25hr

If you have any queries in connection with any aspect of this Service Bulletin, please contact Aston Martin Technical Services on: + 44 (0) 1926 644720 or facsimile: +44 (0) 1926 644733. E-mail: amtech@astonmartin.com Alternatively, please contact your After Sales Manager.

