

FIELD SERVICE ACTION		
To: For the attention of: Please copy to:	All Dealers/Importers The Service Manager The Dealer Principal The Parts Manager Aston Martin Technician(s)	Reference: FSA: 129
Model:	DB9	Issued: September 2005
VIN Range:	(--)0001 to (--)3811	
Subject:	Front Anti Roll Bar Bracket Fixings	Page: 1 of 3

As a result of continuing Quality and Engineering investigations, a potential torque relaxation issue has been identified on the DB9 Front Anti Roll Bar Bracket fixings. To address this issue, please carry out the following workshop procedure.

Service Reception Desk - Essential Vehicle Pre Booking-in Checks

Before taking further action immediately log onto the ODW Warranty System, select the Warranty Live screen (Outstanding Campaigns Status), and using the VIN list range provided check individual VIN's under your control to determine whether any FSA or SAR remains open, including this issue. List them all and plan accordingly.

As the OWD Warranty System operates in real time, the On-Line status reflects the most recent Dealer Warranty Claim submissions.


Always complete this check in advance to pre-secure Parts availability if needed, thus avoiding vehicle down time and customer inconvenience. If necessary, please contact our Warranty & Records department (quoting FSA 129) for clarification, prior to commencing with the following instructions.

Tel:-0044 (0) 1926 644708

Fax:-0044 (0) 1926 644733

Workshop Procedure

- Ensure that the DB9 workshop vehicle protection kit is fitted
- Position the vehicle on a two-post wheel free ramp and raise the vehicle
- Remove the front undertray for access
- Locate the four Front Anti Roll Bar Bracket Fixings (M8 x 20 Flange Head Bolts, Part Number 700123) See the illustration overleaf
- Check and torque the fixings to 24Nm
- Refit the front undertray



FRONT ANTI-ROLL BAR BRACKET FIXINGS (X4)

Warranty Information

<u>Tier</u>	<u>VIN Range</u>	<u>Labour Time</u>	<u>Parts</u>
A	(--0001 to (--3811	0.80 hours	N/A

On completion of this Field Service Action, please ensure that the record section of the Vehicle Owner's Guide is updated to reflect the completion of this instruction.

Any vehicles under your control and any other unmodified vehicles within the affected VIN range that subsequently pass through your workshops must be modified at the earliest opportunity, regardless of whether your Dealership sold the vehicle.

You should also be aware that certain vehicles within the listed VIN range may be affected by previously announced Service Action Campaigns/ Service Field Actions/ Field Service Actions, therefore you should plan your actions so as to avoid customers having to make separate visits to the Dealership.

If you have any queries with any aspect of this Field Service Action, please contact Aston Martin Technical Services on: + 44 (0) 1926 644700/702/703 or facsimile: +44 (0) 1926 644733.

E-mail: stiltma1@astonmartin.com, dhende17@astonmartin.com, nhunter3@astonmartin.com.

Alternatively, please contact your After Sales Support Executive or Customer Service Manager.

Thank you for your co-operation in this matter.

